

Thunderbolt™ 3/USB-C I/O Card

Installation Instructions



Thunderbolt™ 3/USB-C I/O Card

THUNDERBOLT™ 3/USB-C I/O CARD IN THE BOX



Screwdriver



Labeled Door

To install the Thunderbolt 3/USB-C I/O card:

- 1. Turn the Falcon-NEO OFF and disconnect the AC adapter/power supply from the back of the Falcon-NEO.
- 2. Turn the Falcon-NEO upside-down and use the included screwdriver to remove the desired I/O port door:



3. The open I/O port should look like this:



4. Connect the Thunderbolt/USB-C I/O card into the open I/O port. Once the card is connected, attach/connect the 6-pin power cable to the Thunderbolt/USB-C I/O card.




5. Take the labeled door and attach it back to the open I/O port. Use the included screwdriver to re-tighten the screw to the I/O port door.
6. Repeat steps 2 through 5 to install other Thunderbolt/USB-C I/O cards to any of the other available I/O ports.

Once all the Thunderbolt/USB-C I/O cards have been properly installed, the Falcon-NEO can now be used with Thunderbolt/USB-C external drives and storage enclosures. Any connected Thunderbolt/USB-C external drive and enclosure should appear like any other drive.



The Thunderbolt 3/USB-C port is hot-swappable. Please check with the external drive/enclosure's manufacturer to make sure the connected drive/enclosure is hot-swappable.



Technical Support Information

For further assistance please contact
Logicube Technical Support
By phone: **(+1) 818.700.8488, option 3, 8 a.m. – 5 p.m. PT, M-F**
(excluding US legal holidays)
or by email: techsupport@logicube.com